pointed out plumbing work was in process, but it was not for a repipe. Jim Cillo pointed out the owners of 17603 had the plumbing repaired/repiped and he could verify this because Jim was here when they were doing the work. Follow up with Joe Sr will be conducted to obtain more details for specifically what types of plumbing and electrical work is being conducted on each

spreadsheet. The unit Joe Sr. discussed was 17603 Captiva. Joe

update meeting with Elias Brothers Construction (EBC), held at

REVIEW OF UPDATED CONSTRUCTION TRACKING

Joe Sr. initiated the meeting by reviewing the current status

11AM Friday February 3, 2023:

SPREADSHEET:

Emails to myself

Hide

Subscriptions

Receipts

Credits

Trave

**Folders** 

unit. This information will be communicated to all owners soon.

+	New Folder 2016 Football Pool	9
	2017 Football Pool	21
	2022 Hurricane Ca	12
	2022 Hurricane Pl	15
	305 House Sale	21
	4735 Roof	1
	A Publishing	
	Amazon	6
	Anthology	28
	Appeal	
	Aug Comm	1
	Blog Mine	1
	Blog Posts	197
	Book	57
	Bridget	
	Camping	
	Car	2
	Caravan	15
	Charity	
	Coach	1
	College	42
	Computer	5
	Conference	1
	Construction	1
	Critique Group	11
	Disney	7

### RECONSTRUCTION PERMITTING UPDATE:

Joe Sr. indicated they have been tracking the progress of the permit applications through Lee County and a 'hand full' of the permit applications were in review stage now. EBC expects the others to begin review and all be processed soon.

#### STATUS OF UNIT 17632 CAPTIVA:

Joe Sr. noted this unit was listed as on hold. He stated this was the second unit which will have to have permit applications pulled from the process. He indicated this (pulling permit applications) created a money loss issue for them. Joe Sr. was reminded the first unit removed was not because the unit owner opted out (as 17632 Captiva has) and that it was a simple miscommunication between the owner and the Board.

### 17600, 17601/03 UNITS:

Joe Sr. indicated 17601 was nearing completion, with the flooring to be installed possibly the week of 2-6, with trim and cabinets to be installed after flooring. Additional work is also needed for the kitchen and bathrooms, but work could be completed in 2-3 weeks in this unit. Joe Sr. stated the federal standard for installation of vapor barriers will not work in south Florida and that a spray on application is needed for units. EBC is confident insurance will pay for the applications once they discuss this with Mr. Malone.

# 17600, 17601/03 UNITS XACTIMATES REQUESTED FROM DOUG MALONE, FLOOD ADJUSTER:

Roni Elias indicated it would be EBS top prioritize the week of 2-6 to revise the Xactimates they submitted to V.2. and Mr. Malone for initial review and discussion purposes, now that they had a much better idea of what the insurance may allow and what it probably will not. EBC intends to try to get the Xactimates to Section V.2. Board for review, before attaching a revised signed contract for units 17601/03 and sending to Mr. Malone for his review. The plan Mr. Malone laid out in our conference call on 2-1-23 is to have EBC revise the Xactimates and work with EBC to come to an agreement on costs, before submitting to the insurance for final approval. Mr. Malone indicated he wanted individually signed contracts with each unit owner submitted along with the revised estimates. EBC and V.2. Board will need further clarification from Mr. Malone on both of these requests. The adjuster explained during the 2-1-23 call when he receives the revised estimates, it may take 1-2 weeks to submit for final approval, but he would communicate to the final review adjuster the pricing for the submitted estimates should be fairly consistent with the rest of the Xactimates to be approved. Mr. Malone indicated this may help with processing for the estimates submitted after these. Mr. Malone made it clear, final payment may **Donations** Estate Family History 1 Football Pool 1 Ford Escape Foundation 2 **Fundraiser FWA** 25 GCWA Groupon **Gulf Coast Writers** ID Theft Insurance 25 IPV ARC Ins Cert **IPV** Board 2 **IPV Elias IPV Elias Corres IPV Elias Legal IPV Elias Owners IPV** Financials 11 **IPV** Insurance **IPV** Legal IPV Owner **IPV Property M** IPV Rebuild 3 **IPV** Roofs

not be for 4-6 months because of the extremely large volume of claims being submitted.

### **QUESTIONS - OPEN DISCUSSION:**

The floor was opened to anyone who had any questions or wanted to discuss anything from the meeting. Jim Cillo asked if the plan for these meetings and updates was still the same, in that a conference call would be bi-weekly and an updated progress spreadsheet would be emailed in between calls. No updated spreadsheet was received on 1-27, after the last conference call on January 20th. EBC apologized for missing the update and assured everyone would be updated according the the framework agreed upon.

No other questions or comments came up about the meeting, except a request to talk separately with Roni, Rami, by Rick R to discuss better communications and assurances on insurance coverage and no potential uncovered costs being incurred by any unit owners or the Association Board. These issues are still being addressed with EBC and will be communicated with owners soon.

Jennifer, Rita and Ed, please feel free to add anything I missed.

Please let me know if you have any questions, or would like to discuss anything regarding this meeting.

Thank you, Rick



### **Sue Carlton**

From:

lon

suenipv@gmail.com **To:** Rick Roudebush

Cc: Andrea Calcagno,

Danilo Fior,

Edward Walendy,

Elaine Minnis,

George McCann


and 23 more...

Thanks for the update.

> Show original message



## **ISLAND PARK - #001217**



Spirit		, Ginny Howley
Spred	15	,
Steve	2	Meghan Damian and 23 more
Tax	4	
Travel	11	My apologies to all. I meant to attach the updated spreadsheet showing current status for each phase of reconstruction. IP = in progress. If you have any questions about your specific
Unwanted		unit, please let me know. I will try to obtain an answer for you. We
Verizon	35	are still working on improving communications between ECB and Sec V.2.
Wells	145	Rick
wheelchair		> Show original message
WIP	4	

2.3.23 Island....pdf

542.6kB

				Island Park 5.2				Updated 2.10.23								
Captiva Isl	and Ln.															
Unit#	Priority#	Plumbing completed		Needs repipe to code	Electric completed		Loaded	Prepped for drywall		Hung	Finished	Floors start approx.	Trim starts approx.	Interior Paint	Cabinets start approx.	
17600	2	Yes	Verified	Yes	Yes	Verified	Yes	Yes	Verified	Yes	Yes					
17601	1	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes	2/13/2023	2/16/2023		TBD	
17602	3	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes					
17603		Yes	Verified	no	Yes	Verified										
17611	8	Yes		no	pending		10-Feb			2/13-2/17						
17613	9		has resident	no	Yes	Verified	Yes	Yes	Yes	Yes	in progress					
17620		Yes		no	pending											
17631		Yes	Verified	no	pending											
17632	HOLD	pending		no	Yes	Verified										
17633	ROOF	pending		no	in progress											
17641	7		has resident	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes					
17642		Yes	Verified	no	pending											
17643		Yes	Water Heater	no	Yes											
17653	11	Yes		Yes	pending											
Marco Island Ln																
Unit#	Priority#	Plumbing completed		Needs repipe to code	Electric	completed	Loaded	Preppe	ed for drywall	Hung	Finished	Floors	Trim		Cabinets	
17601	4	Yes	Verified	Yes	Yes		Yes	Yes	Verified	2/13-2/17						
17623	12	Yes needs water heater deck		Yes	Yes					this will hold until approved by adjuster						
17633		Yes		no	pending											
17641	5	Yes has resident		no	Yes	Verified	Yes	Yes	Verified	Yes	Yes					
17643	6	Yes has resident		no	Yes	Verified	Yes	Yes	Verified	YES	in progress					
17651		pending	repairs pending	Yes	yes	verified	10-Feb			TBD due to plumbing						

#### notes:

17651 marco needs repipe to code. Is the owner doing this?

Engineer has provided preliminary report for 17643 marco reference 1/2" floor sag. We will provide a copy forthcoming. It is not storm related this will be extra to repair if requested. Extra will include engineering fees. Engineer an hour ago has provided a very preliminary report to n the roof repair. In order to move forward with details he needs to be but under contract by EBC.

We are finding old water intrusion issue non storm related. Rotted wood etc. we are compiling a list with photos for review and these repairs will need to be authorized for payment outside the insurance covered scope of work. List and photos forthcoming next week

As of today ebc requests all information communication, question, etc be funneled through only Rick and one other board member. It has become unmanagable for ebc to deal with individual owners calls, emails, texts.please advise whom other than Rick is the secondary point of contact.

Ebc requests that all questions about the project be sent to us via email by one of the 2 points of contact in a list format so we can respond by Thursday of which will allow time of rus to update and make notes on this weekly provided updates every Friday.

				Island Park 5.2			Updated 2.10.23								
Captiva Isl	and Ln.														
Unit #	Priority #	Plumi	bing completed	Needs repipe Electric completed		Loaded	Prepped for drywall		Hung	Finished	Floors start approx.	Trim starts approx.	Interior Paint	Cabinets start approx.	
17600	2	Yes	Verified	Yes	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17601	1	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes	2/13/2023	2/16/2023		TBD
17602	3	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17603		Yes	Verified	no	Yes	Verified									
17611	8	Yes		no	pending		10-Feb			2/13-2/17					
17613	9		has resident	no	Yes	Verified	Yes	Yes	Yes	Yes	in progress				
17620		Yes		no	pending										
17631		Yes	Verified	no	pending										
17632	HOLD	pending		no	Yes	Verified									
17633	ROOF	pending		no	in progress										
17641	7		has resident	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17642		Yes	Verified	no	pending										
17643		Yes	Water Heater	no	Yes										
17653	11	Yes		Yes	pending										
Marco Island Ln															
Unit#	Priority#	Plumbing completed		Needs repipe to code	Electric	completed	Loaded	Preppe	ed for drywall	Hung	Finished	Floors	Trim		Cabinets
17601	4	Yes	Verified	Yes	Yes		Yes	Yes	Verified	2/13-2/17					
17623	12	Yes needs water heater deck		Yes	Yes					this will hold until approved by adjuster					
17633		Yes		no	pending										
17641	5	Yes has resident		no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17643	6	Yes has resident		no	Yes	Verified	Yes	Yes	Verified	YES	in progress				
17651		pending	repairs pending	Yes	yes	verified	10-Feb			TBD due to plumbing	•				

#### notes:

17651 marco needs repipe to code. Is the owner doing this?

Engineer has provided preliminary report for 17643 marco reference 1/2" floor sag. We will provide a copy forthcoming. It is not storm related this will be extra to repair if requested. Extra will include engineering fees.

Engineer an hour ago has provided a very preliminary reprtrt on the roof repair. In order to move forward with details he needs to be bput under contract by EBC.

We are finding old water intrusion issue non storm related. Rotted wood etc. we are compiling a list with photos for review and these repairs will need to be authorized for payment outside the insurance covered scope of work. List and photos forthcoming next week

As of today ebc requests all information communication, question, etc be funneled through only Rick and one other board member. It has become unmanagable for ebc to deal with individual owners calls, emails, texts.please advise whom other than Rick is the secondary point of contact.

Ebc requests that all questions about the project be sent to us via email by one of the 2 points of contact in a list format so we can respond by Thursday of which will allow time of rus to update and make notes on this weekly provided updates every Friday.

# ISLAND PARK VILLAGE, SECTION VII, CONDOMINIUM ASSOCIATION, INC.

C/O Pegasus Property Management 8840 Terrene Court, Suite #102 Bonita Springs, FL 34135

AGENDA ELIAS BROTHERS BIWEEKLY MEETING Tuesday, July 30, 2024

1. Repiping - Discussion a. 17601 Marco

2.

			Island Park 5.2	!		Updated 2.17.23									
Captiva Isl	and Ln.														
Unit #	Priority #	Plumbing completed		Needs repipe to code	Electric completed		Loaded	Prepped for drywall		Hung	Finished	Floors start approx.	Trim starts approx.	Interior Paint	Cabinets start approx.
17600	2	Yes	Verified	Yes	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17601	1	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes	2/13/2023	2/21/2023		TBD
17602	3	Yes	Verified	no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17603		Yes	Verified	no	Yes	Verified	22-Feb	on	22-Feb	week of 2/20					
17611	8	Yes		no	yes	Verified	10-Feb	yes		18-Feb	in progress				
17613	9	Yes	has resident	no	Yes	Verified	Yes	Yes	Yes	Yes	yes				
17620		Yes	Verified	no	yes	Verified	21-Feb	on	21-Feb	week of 2/20					
17631		Yes	Verified	no	yes	Verified	20-Feb	on	20-Feb	week of 2/20					
17632	HOLD	pending		no	Yes	Verified									
17633	ROOF	pending		no	in progress										
17641	7	Yes has resident		no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17642		Yes	Verified	no	pending										
17643		Yes	Water Heater	no	Yes										
17653	11	Yes		Yes	pending										
Marco Island Ln	).											Т			
Unit #	Priority #	# Plumbing completed		Needs repipe to code Electric comple		completed	Loaded	Preppe	ed for drywall	Hung	Finished	Floors	Trim		Cabinets
17601	4	Yes	Verified	Yes	Yes		Yes	Yes	Verified	18-Feb	in progress				
17623	12	Yes needs	s water heater deck	Yes	Yes					this will hold until approved by adjuster					
17633		Yes		no	pending										
17641	5	Yes has resident no		no	Yes	Verified	Yes	Yes	Verified	Yes	Yes				
17643	6	Yes has resident n		no	Yes	Verified	Yes	Yes	Verified	YES	yes				
17651		pending	repairs pending	Yes	yes	verified	10-Feb			TBD due to plumbing					

## notes:

17651 marco needs repipe to code. EBC we will provide quote for re-pipe early next week

17653 Captiva EBC provided quote for re-pipe and letter as requested was sent on 2/15 this week and has not been responded to.

Engineer has provided preliminary report for 17643 marco reference 1/2" floor sag and It is not storm related this will be extra for EBC to repair if requested. Extra will include engineering fees. Homeowner performing work by others.

Engineer an hour ago has provided a very preliminary report on the roof repair. In order to move forward with details he needs to be put under contract by EBC. PENDING DIRECTION TO PROCEED.

We are finding old water intrusion issue non storm related. Rotted wood etc. we are compiling a list with photos for review and these repairs will need to be authorized for payment outside the insurance covered scope of work. List and photos forthcoming next week

As of today ebc requests all information communication, question, etc be funneled through only Rick and one other board member. It has become unmanagable for ebc to deal with individual owners calls, emails, texts.please advise whom other than Rick is the secondary point of contact. Ebc requests that all questions about the project be sent to us via email by one of the 2 points of contact in a list format so we can respond by Thursday of which will allow time of rus to update and make notes on this weekly provided updates every Friday.

17631 CAPTIVA owner teresa was email requestin phone # and tim to call her to answer questions. Email not reponded to home stocks insulation drywall on Monday 2/20/23 as noted above.

As shown above shaded in light beige 17631 Captiva - 17620 Captiva & 17621 Captiva all will be stocked with insulation and d/w and prepped and will be started next week.